

Fig. 1




Fig. 2a

# GENERIC FRACTURE CLASSIFICATION DISTAL RADIUS

TYPE

(LAT) PATTERN (PA VIEW)

A  
EXTRA ARTICULAR



Fig. 2b

B  
MARGINAL




Fig. 2c

C  
INTRA ARTICULAR




Fig. 2d




Fig. 4




Fig. 7




Fig. 6




Fig. 3




Fig. 8




Fig. 5













Fig. 9



20172024562007



2007-24464001




Fig. 20




Fig. 22

Fig. 23




Fig. 21




Fig. 24

Fig. 25




Fig. 26




Fig. 27











Fig. 28

2044T20-246E2001







2014T20-246E/001



2024-04-24 14:00:00





2014 T 20 246 E 200 F




Fig. 45




Fig. 46

















Fig. 47



201720245001





204720-2452007

